

1/12




FIG. 1

2000-07-06 09:10:39

2/12




FIG. 2

3/12




FIG. 3

4/12




FIG. 4A

20E0T0" 6E90T650

5/12




FIG. 4B

20E0T0"6E90T660

20E0T0" 6E90T660

6/12




FIG. 5

7/12




FIG. 6

8/12





FIG. 7



9/12



FIG. 8





10/12




FIG. 9

20E010" 6E90T660

11/12




FIG. 10




FIG. 11